

Digital Vehicle Inspection

Gleniti Auto Services

356 Wai-iti Road

643-686-0835

www. glenitiautos.co.nz

Gleniti Auto Inspection

Customer:		License:	
Vehicle:	Subaru Forrester	VIN:	
Inspection date:	5/27/2015	Odometer:	in: 249,034- km
Repair Order #:		Technician:	Harry Newmarch

We have inspected your vehicle with the following results:



Harry Newmarch, Technician

Ok		
Fluids	Observation	Action
Brake Fluid	Good	
Engine Coolant	Good	

Ok			
Filters, Battery, Belts, and Radiator Hose			
✓ Belts: Serpentine/VBelts	✓ Radiator Hoses	✓ Timing belt	
Lights, Wiper Blades			
✓ Warning Lights	✓ Turn Signals	Headlights/foglights	
✓ Licence Plate Lights(s)	✓ Reverse Lights	✓ Brake Lights	
✓ Wiper Blades	✓ Glazing		
Fluids			
✓ Fluid Leaks	✓ Windscreen Washer Fluid		
Tires, Brakes & Wheels			
✓ Tire Rotation	✓ Brakes: Rear	✓ Wheel Bearings	
✓ Left Front Tyre	Right Front Tyre	✓ Right Rear Tyre	
✓ Left Rear Tyre			
Under Car			
✓ Shocks/Struts	✓ Control Arm Bushings	✓ Tie Rods	
✓ Ball Joints	✓ Axles,Driveshafts,Mounts		



Maintenance		
Under Car	Observation	Action
Sway Bar Links/Bushings	Worn Image(s): http://tinyurl.com/ojf6gwe Right-hand mouse-click on link and select 'Open Link in New Tab'	Replace sway bar links

Bad		
Filters, Battery, Belts, and Radiator Hose	Observation	Action
Battery	Failed Load Test Cca 329 /470	Replace Battery
Fluids	Observation	Action
Power Steering Fluid	Dirty	Power Steering Flush Recommended
Tires, Brakes & Wheels	Observation	Action
Brakes: Front	<15% Image(s): http://tinyurl.com/po64ck3 Right-hand mouse-click on link and select 'Open Link in New Tab'	Replace Brake Pads

Requires Immediate Attention			
Fluids	Observation	Action	
Engine Oil	Dirty Overdue by 4000 km	Change Oil	
Transmission Fluid	VERY Dirty Image(s): http://tinyurl.com/opf8ey7 Right-hand mouse-click on link and select 'Open Link in New Tab'	Auto Transmission Flush Recommended	



Additional Information



Transmission Fluid



Brakes: Front





Sway Bar Links/Bushings